

A Sonic

CLEANING CONCENTRATE FOR
USE IN ULTRASONIC CLEANERS

CLEANING CONCENTRATE FOR CARBURETORS

Product: AS-CARB-... / Quantity: ... litre

Use: **Concentrate has to be added in ratio 10% to water.** We recommend using deionised / de-mineralized water. You can make 10L of solution from 1L of concentrate. **Operating temperature should be between 50 - 80°C.** Strong concentrate with low alkaline value. Removes contaminants including: general soiling, carbon and grease. Safe on brass, aluminum and other sensitive metals.

KEEP OUT OF REACH OF CHILDREN!

Contains hazardous substances: Sodium metasilicate pentahydrate.

H290 - May be corrosive to metals. H314 - Causes severe skin burns and eye damage. P280 - Wear protective gloves/protective clothing/eye protection/face protection. P305+351+338: IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. P303+361+353: IF ON SKIN (or hair): Remove immediately all contaminated clothing. Rinse skin with water/shower. P301+330+331: IF SWALLOWED: rinse mouth. Do NOT induce vomiting. P310 - Immediately call doctor or a POISON CENTER. P363 - Wash contaminated clothing before reuse. P501 - Dispose of contents in accordance with national legislation.

DANGER



GHS05

Distributor: AVene d.o.o., Tržaška cesta 134, Ljubljana, Slovenia, EU
Contact: t: + 386.41.566.618, e: prodaja@avene.si